



Shower Tub

**Please read whole manual before You start.
All given measurements are in millimeters.**




Shower Tub



Details list




Shower Tub



I





6 x I
Drill holes Ø4mm before screws.




II


1



Shower Tub




Shower Tub




52 x F

Use water level!




7 x Det 5


Remove Det 4 and place it against Det 5.



8 x Det 5






7 x Det 5




4 x Det 5


Shower Tub




Shower Tub




4 x I
Drill holes Ø4mm
before screws.



I








II




III

2 x F

Shower Tub




During assembly and retightening
the threaded rods, use oil (Würth HSP 1400
or similar) to avoid "cold welding"
and it is also easier tightening.





**Tighten
Details 9.**

IV


Shower Tub




I



II



III



IV